

Abbildung 1: When casting the wall, make the windowow opening as shown in the sketch. The values shown are given in a seperate document "work-drawing".



Abbildung 2: Pool beeing build, circular wall opening beeing prepared



Page 1 of 6




Abbildung 3: The picture shows a foto with the round opening. The green liner on top of the concrete opening is already prepared.



Abbildung 4: As an example the picture shows three round windows with pressure flange

rubber 1





2 component PU foam instead of grout -It is easier and faster



Abbildung 6: The window is lifted into the window opening



Page 3 of 6



Abbildung 7: Foto shows dry side (the observation side) of the window. Make sure the window sits flush with the wall. Fasten the window with screws/wallplugs.



Abbildung 8: The space besides the window block is filled with 2 component polyurethane foam





Abbildung 10: Make holes in (green) liner with a power drill – using a large steel drill. Cut remaining parts with sharp cutter knife.



Page 5 of 6



Abbildung 11: One rubber between liner and acrylic block (rubber 2). One rubber between liner and steel blind (rubber 1). Steel blind on top. Fasten all starting at the top of the window.



Abbildung 12: Finish! Now you can cut of the green liner on the inner side of the steel flange.



Page 6 of 6